

REPAIR KITS

- <u>Home</u>
- FAQ
- Repair Parts
- Splicing Procedure
- Feedback


Back to Results Print

I004

Full Repair Kit: 68459241AA

No terminal repair kits have been identified.

End View



Isometric View

1 z 3 02.09.2021, 11:20



Removal Tools

A specific removal tool has not been identified.

Pin Information

Cav	Circuit	Gauge	Color	Function
1	A901	2.5	PK	FUSED B(+)
2	Z331	2.5	WH	GROUND
3	P188	1	BK	PASSENGER FRONT SEAT HEATER CONTROL
5	A214	0.5	RD/GN	FUSED B(+)
6	Z341	0.5	WH/DB	GROUND
13	D158	0.35	BU/BK	CAN IHS (-)
14	D157	0.35	PK/DB	CAN IHS (+)
15	R57	0.5	GN	DRIVER SEAT BELT BUCKLE SWITCH SENSE
16	R730	0.5	WH	PASSENGER SEAT DETECTION RETURN
20	R730	0.35	OG	PASSENGER SEAT DETECTION RETURN
21	R263	0.35	PK/BK	DRIVER SEAT POSITION SENSOR VOLTAGE
22	R7	0.5	GN/YE	LEFT SEAT THORAX SQUIB 1 LINE 1
23	R5	0.5	OG/BK	LEFT SEAT THORAX SQUIB 1 LINE 2
24	Z331	0.5	BK	GROUND
25	P968	0.5	YE/DB	HEATED SEAT SENSOR RETURN
26	P688	0.5	GY/RD	PASSENGER FRONT HEATED SEAT TEMP SENSE
27	C91	1	GY	HEATED STEERING WHEEL FEED
28	A214	0.5	BU/RD	FUSED B(+)

2 z 3 02.09.2021, 11:20

Mopar Connection Repair Kit

Cav Circuit Gauge Color

Function

28 A214 0.5 RD FUSED B(+)



Mopar is a registered trademark of Chrysler Group LLC. © Copyright 2011 Chrysler Group LLC. All Rights Reserved. Chrysler, Jeep, Dodge, Ram, Mopar and the Pentastar logo are registered trademarks of Chrysler Group LLC. FIAT is a registered trademark of Fiat Group Marketing & Corporate Communication SpA, used under license by Chrysler Group, LLC. GEM and design is a registered trademark of Chrysler Group Global Electric Motorcars LLC, a wholly owned subsidiary of Chrysler Group LLC. ©2011 Chrysler Group LLC, All Rights Reserved. v1.5.4 Built:09/14/2020

3 z 3 02.09.2021, 11:20