

FALLO DE LOS MICRO-RELÉ

EN BODY MAGNETI MARELLI

FIAT PALIO/SIENA 2005

1365464663 13:40:48
HBC 178.73 2T
28/07/06

80055202155000
MAGNET
980
A80
5502155000
28/07/06

MAGNET
MARELL
51771326 209/2906
5018697300000
NRC 178.73
12V =
C144

>PP-TD20<


pedido 30003430101
Cliente 097013-2
20060807
1712639372


MAGNET
MARELLI

>PP-TD20<
MAGNET
MARELLI

MAGNET
MARELLI
51771326 20912906 12V =
501869130000
MSC 178.73
C144

**DATOS DEL INMOVILIZADOR, LLAVES,
PIN CODE
MICRO MOTOROLA MC9S12DG256B**






**RELÉ ACTIVADOS POR EL BODY PARA
ENCENDER LUCES DE GIRO, UNO PARA CANAL
DERECHO Y OTRO PARA CANAL IZQUIERDO**

REEMPLAZO DE RELÉ DE LUCES DE GIRO


- **Cómo no se consigue reemplazo original para cambiar los micro-relé ,ya que son más pequeños de los que se encuentran en el mercado.**
- **Optamos por armar una plaqueta exterior con micro-relé del mercado.**
- **El problema lo resolvemos de una forma un poco artesanal pero eficiente.**




09.19.2008


 **SANYO** CS4A
 **FAL**^{US} 
12A 125VAC 7A 250V~
28VDC 28V~
 7A 250V~
SRD-S-112D

 **SANYO** CS4A
 **FAL**^{US} 
12A 125VAC 7A 250V~
28VDC 28V~
 7A 250V~
SRD-S-112D





09 19 2008



09.19.200