			Test results	1	
1	COMPONENT CONCERNED	CHECK THE UNIAIR MODULE INLET OIL FILTER	OK (NO FAULTS DETECTED)	FAULT DETECTED	OPERATION
	Uniair module inlet oil filter	Check the condition of the MultiAir module inlet oil filter	Go to Step 2	Oil filter clogged	Replace the filter [PR_1036F22]
2	COMPONENT CONCERNED	OIL PUMP OPERATION CHECK	OK (NO FAULTS DETECTED)	FAULT DETECTED	OPERATION
	Oil pump	Check that the engine oil pump is working properly	Go to Step 3	Incorrect operation of the engine oil pump	Replace the engine oil pump
3	COMPONENT CONCERNED	CHECK OPERATION OF UNIAIR MODULE ENGINE OIL TEMPERATURE SENSOR	OK (NO FAULTS DETECTED)	FAULT DETECTED	OPERATION
	Uniair module oil temperature sensor	Check the correct operation of the Uniair module engine oil temperature sensor	Go to Step 4	Incorrect operation of temperature sensor	Replace the Uniair module engine oil temperature sensor Op. 1036F21 UNIAIR MODULE OIL TEMPERATURE SENSOR - R.R.
4	COMPONENT CONCERNED	ENGINE MANAGEMENT CONTROL UNIT OPERATION CHECK	OK (NO FAULTS DETECTED)	FAULT DETECTED	OPERATION
	Engine management control unit	Check that the engine management control unit is working properly	End of diagnosis	Incorrect operation of engine management control unit	Replace the engine management control unit <u>Op. 1056B82</u> <u>INJECTION/IGNITION</u> <u>SYSTEM E.C.U.</u> (ONE) - R + R